

Bill no: 1st & final

M. A. R. 57 (Rule 116)
Measurement Book

No. D

63688

Serial No.

Name of work From To

Name of Contractor of nature of Agency..... Sri. Nagaraj. K.

Date of commencement of work.....

Date 1	Full description, etc, of work 2	Dimensions				Contents 7	Reference to last Measurement 8
		Number 3	Length 4	Breadth 5	Depth 6		
	Name of work: Repair Reconstruction of damaged culvert in Dasarahalli in ward no: 15 Est: ward crd R: 15,00 lakh Job code NO: 015-20-000111 AS NO: EE/DD/AS/88/2020-21 TS NO: EE/DD/TS/20/2020-21 25.0 NO: EE/DD/NO/21/2020-21 date 5/11/2020. <i>[Signature]</i>						

MEASUREMENT BOOK

MEASUREMENT BOOK							Reference to last Measurement
Date	Full description, etc, of work	Dimensions				Contents	8
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	
	1) Earth work excavation for foundation of bridge water supply, sanitary lines and electrical conduits in hard soil not exceeding 1.5m in depth etc complete as per specification BF per measurement recorded in this MB vide page No: 63692						12303-00 12312-00
	2) Paving & laying plain cement concrete at ratio 1:3:6 with OPC @ 220 Kgs with crushed stone aggregate 40mm & all graded granite metal machine made coarse laid in layer not exceeding 15cm thick well compacted, curing etc complete as per specification						

ಸಹಾಯಕ ಕಾರ್ಯದರ್ಶಿ ಅಭಿಯಂತರರು
೩೩ ದಾಸರಹಳ್ಳಿ ಅಂಚು ವಿಭಾಗ

M. A. R. 57 (Rule 116)
Measurement Book

No. D

63680

Serial No.

Name of work From To

Name of Contractor of nature of Agency..... From To

Date of commencement of work.....

Date 1	Full description, etc. of work 2	Dimensions			Contents 7	Reference to last Measurement 8
		Number 3	Length 4	Breadth 5		
	BF for measurement Recorded in this B vide page no: 63694 ie 19.44 m ³ @ Rate Rs 4000/- m ³					R 77760=0
	3) Providing & laying plain (reinforced) cement concrete for side drains using M-20 nominal mix concrete with OPC @ 300 kg with 20mm & 40mm graded sand metal coarse aggregate @ 0.69 cum & fine aggregate @ 0.43 cum etc complete as per specification Culverts For Rate work ① 4th cross vide	1	5.00	2.10	0.20	2.20

ಸಹಾಯಕ ಕಾರ್ಯದರ್ಶಿ, ಆರೋಗ್ಯ ಮತ್ತು ಕುಟುಂಬ ಕಲ್ಯಾಣ ಇಲಾಖೆ, ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ, ಬೆಂಗಳೂರು - 560 057.

MEASUREMENT BOOK

1	Full description, etc., of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
2	3	4	5	6	7	8	
② 5th Corn Vidhya Nagar	1	7.50	2.20	0.20	3.15	3.30	
③ Ragnorth road	1	5.60	1.80	0.20	1.80	2.25	
④ 2nd Corn	1	5.60	1.50	0.20	1.50		
⑤ F/s of Mageed	4	4.20	2.10	0.20	1.76		
⑥ Near Standard school	1	5.40	2.10	0.20	2.27		
⑦ Near Chapalmore road	3	5.60	2.10	0.20	2.31		
For Rce drain	1	30.0	1.05	0.15	4.73		
For Rce drain	1	4.60	1.05	0.15	0.63		
For side wall	1	18.0	1.05	0.15	2.84		
4th Corn Vidhya Nagar	2	5.60	0.30	0.90	2.70		
5th Corn	2	7.50	0.30	0.95	4.28		

M. A. R. 57 (Rule 116)
Measurement Book

No. D

63600

Serial No.

Name of work From To

Name of Contractor of nature of Agency.....

Date of commencement of work.....

1	Full description, etc., of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
2	3	4	5	6	7	8	
3) Ragnorth road	2	5.60	0.30	1.0	3.4		
4) 2nd Corn	2	5.60	0.30	1.05	3.45		
5) F/s of Mageed	2	4.20	0.30	1.0	2.52		
6) Near Standard school	2	5.40	0.30	0.95	3.08		
7) Chapalmore road	2	5.60	0.30	1.10	3.70		
For Rce drain	2	30.0	0.15	0.61	5.81		
For Rce drain	2	4.60	0.15	0.61	0.78		
For side wall	2	18.0	0.15	0.61	3.51		
4th Corn Vidhya Nagar	1	5.60	2.10	0.25	2.63		
For Rce drain	2	5.60	0.60	0.15	0.60		

MEASUREMENT BOOK

Date	Full description, etc., of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	5 th LOD Vidyasagar	1	7.50	2.0	0.25	3.75	
	For Repair	2	7.50	0.60	0.15	0.68	1.35
	3) Raghunath Road	1	5.00	1.70	0.25	2.13	
	For Repair	2	5.00	0.60	0.15	0.90	
	4) 2 nd Corridor	1	5.00	1.40	0.25	1.75	
	For Repair	2	5.00	0.60	0.15	0.90	
	5) Flydy road	1	5.20	2.0	0.25	2.10	
	For Repair	2	5.20	0.60	0.15	0.76	
	6) Near Standard School	1	5.40	2.0	0.25	2.70	
	For Repair	2	5.40	0.60	0.15	0.97	
	7) Near Chappanmatta	1	5.60	2.0	0.25	2.82	
	For Repair	2	5.60	0.60	0.15	1.01	
						30.12	

M. A. R. 57 (Rule 116)
Measurement Book

No. D

63631

Serial No.

Name of work From To

Name of Contractor of nature of Agency

Date of commencement of work

Date	Full description, etc., of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	BF Total Diffy 80.42 to 80.19						
	@ Rate Rs 4500/-						R 3,60,256 = 0
	4) Supplying fixing & placing TOTT steel bars for						
	Reinforcement in super structure concrete work						
	BF Reinforcement recorded in form 10A						
	vide page no: 63636						
	ie 8.02 Tons @ Rate Rs 58,000/-						R 4,65,160 =
	5) Disposal of debris to the final place of disposal in						
	all load and lift and as directed by the Engineer						
	for charge of the work						

63692

Date	Full description, etc., of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
	<u>Bordier</u>  culmet  Recdow Rag: 101/11 Road  2nd  2nd 29/08/21		 5th  4th Kalugam 200 Temple Road			 K K Road  Magid  Dwarabali Road  Chappu 29/08/21	

MEASUREMENT BOOK

Date 1	Full description, etc, of work 2	Dimensions				Contents 7	Reference to last Measurement 8
		Number 3	Length 4	Breadth 5	Depth 6		
	Audited and admitted for Rs <u>1031808/-</u> Passed by Cheque for Rs <u>971142/-</u> <u>Nine Lakhs Seventy one Thousand</u> <u>one hundred and Forty two Rupees</u> by adjustment Rs <u>60666/-</u> only Accountants Superintendent B.B.M.P. Dasarahalli Division Exe. Engineer					1st and Final → 1031808-∞ IT → 10318-∞ LWC → 10318-∞ CBF → 1032-∞ Rty → 15162-∞ Fire → 5410-∞ ceST → 9213-∞ seST → 9213-∞ Dealt(-) 60666-∞ Net → 97,1142-∞	